



AGENDA
DISTRICT OF PORT HARDY
COMMITTEE OF THE WHOLE MEETING
5:45 pm TUESDAY AUGUST 9, 2016
COUNCIL CHAMBERS, MUNICIPAL HALL
7360 COLUMBIA STREET

Mayor: Hank Bood
Councillors: Pat Corbett-Labatt, Dennis Dugas, Jessie Hemphill, Rick Marcotte, Fred Robertson, John Tidbury

Staff: Allison McCarrick, Chief Administrative Officer; Heather Nelson-Smith, Director of Corporate Services; Abbas Farahbakhsh, Director of Operational Services; Adrian Maas, Director of Financial Services

<u>Page</u>		Time:
	A. CALL TO ORDER	
	B. APPROVAL OF AGENDA	
	Motion required	1. 2.
	C. DELEGATION	
	No delegation	
	D. STAFF REPORTS	
	1. Leigh Stalker, Strategic Natural Resources (August 4/16) re: Community Wildfire Protection Plan	
	2. Allison McCarrick, CAO (July 11/16) and Doug McCorquodale, Pacificus Biological re: Port Hardy Seagate Pier Inspection Report – Onsite Engineering Ltd. dated June 30,2016	
	Motion / direction	1. 2.
	3. Abbas Farahbakhsh, Director of Operations (August 4/16) re: Shutters for Port Hardy Museum	
	Motion / direction	1. 2.
	E. NEW BUSINESS	
	No New Business	
	F. ADJOURNMENT	
	Motion required	1. 2.
		Time:



Presentation Handout for District of Port Hardy

August 4, 2016

Re: Community Wildfire Protection Plan for the District of Port Hardy

Presented by: Strategic Natural Resource Consultants Inc.

Contact: Allison McCarrick, Chief Administrative Officer, District of Port Hardy

Key Findings:

- A far majority of the fires in the area are human-caused; indicates there is potential for reduction of wildfires with various prevention strategies that consider education and enforcement activities
- Concerns of local stakeholders: recreation in the forest surrounding the community, private and industrial land clearing and operations
- Most areas scored a low or moderate Wildfire Behaviour Threat Class; those areas that resulted in a high or extreme Wildland Urban Interface Threat Class are small and have various features surrounding them that help to reduce the overall threat in the area
- Public education on FireSmart would be valuable and worthy

Recommendations:

- Education: enhance public knowledge, strengthen wildfire suppression training, improve local operational knowledge
- Engineering: encourage FireSmart principles on private properties, consider a fuel management demonstration project, conduct FireSmart assessments on critical infrastructure and implement FireSmart principles if required
- Enforcement: consider incorporating FireSmart principles into building and property standards and subdivision layout, consider interface Development Permit applications go through applicable external agencies/groups for comment



DISTRICT OF PORT HARDY

STAFF REPORT



DATE: July 11, 2016
TO: Mayor and Councillors
FROM: Allison McCarrick, Chief Administrative Officer
RE: Seagate Pier Inspection

PURPOSE

To provide Mayor and Council with a summary of the Seagate Pier review completed by Onsite Engineering Ltd. and Pacificus Biological Services Ltd.

BACKGROUND

The Seagate Pier facility is a well used facility by the residents of Port Hardy and surrounding communities. It is an entry point into the municipality by water and is part of the downtown core. This facility is an economic driver for the District with its mooring, offloading, building lease arrangements and future possibilities. District Council authorizes an annual Capital budget for major repairs to this facility. The Seagate Pier review was completed to substantiate future funding and direction of that funding.

ANALYSIS

The pier inspection was limited to the pier approach, pier head, gangway and two floats. Onsite Engineering Ltd. inspected the pier components above the current low water at the time and Pacificus inspected the submerged portion of piles and bracing.

The inspection was performed with a top down approach, visually inspecting the asphalt surfacing, decking, stringers, cap beams, piles and bracing. Sounding/coring of various components was completed where necessary.

Ten recommendations, priority and cost were noted. Four of the recommendations are currently underway. The following six are the balance of the noted recommendations:

Repair description	Recommendation	Timing	Estimated Cost (2016 \$)
Seal Asphalt	Repair should precede repairs to structural components below deck to maximize lifespan of new members and reduce the rate of further deterioration of existing members.	0-1 years	2,870
Repair Bracing	Repairing all bracing at once will best utilize having construction and staging equipment on site.	0-1 years	68,860
Lash Fender Piles	The fender piles should be lashed. This can be done from the pier deck by using a Hiab to tighten/install lashing.	0-2 years	11,990

¹ Port Hardy Seagate Pier Inspection Report, Onsite Engineering Ltd., June 30, 2016

Repair description	Recommendation	Timing	Estimated Cost (2016 \$)
Banding, Fish-plating, Replace Stringer	Completing all banding, fish-plating, stringer replacement at once will best utilize having construction and staging equipment on site.	0-3 years	114,180
Re-anchor Lamppost	Replace current C-channel bracing with 10"x 20"x 1/2" steel plating or 20" long 10" C-channel. If C-channel is used face flange side down.	0-5 years	1,030
Replace Bent 58	Will require considerable work and special equipment onsite.	0-5 years	132,275

FINANCIAL IMPLICATIONS

Period of time	Approximate cost	Budget year
0-2 years	83,720	2017
0-3 years	114,180	2018
0-5 years	133,305	2019

- Cost estimate excludes mobilization costs
- Additional efficiencies in cost will be achieved if the banding, fish-plating, stringer replacement is completed with the bracing repair.


SUMMARY

- No mooring on the eastern end of the pier until Bent 58 is replaced ("No-mooring" signage currently in place, cleat to be removed)
- Timber floats 1 & 2 are currently under repair and the cost is included in the 2016-2020 Financial Plan
- Asphalt sealing - high priority for protection of the materials below the deck
- Bracing - 104 components affected
- Cap beams on pile bents - 7 bents affected
- Stringers on pile bents - 11 stringers affected
- Re-anchor lampposts - minor repair
- Bent 58 - Poor condition - major issues occurring at this bent
- After repairs are completed the pier will safely moor large vessels
- A qualified registered professional is required to complete construction inspections during and after completion of the following programs:
 - Bracing program
 - Banding, fish-plating, stringer replacement program
 - Bent 58 replacement program

STAFF RECOMMENDATION

"Direct staff to include the costing contained in this report in the 2017-2021 Financial Plan finance meeting discussions for further review."

Respectfully submitted,



Allison McCarrick
Chief Administrative Officer

Table 6.0. Summary of recommendations, priority and expected cost to rectify issues identified during Seagate pier inspection.

Project #	Timing	Repair	Additional Timing Information	Number Of Components Affected	Estimated Cost (\$)*
N/A	N/A – Repairs In Progress	Replace Float Billet	N/A – Repairs In Progress	1	N/A – Repairs In Progress
	N/A – Repairs In Progress	Reduce Play Around Float Dolphins	N/A – Repairs In Progress	2	N/A – Repairs In Progress
1	Immediately	Remove Mooring Cleat on Eastern End Of Pier	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Should Occur Immediately To Reduce Risk Of Damage To Pier.	1	\$450
1	Immediately	Sign “No Mooring At End Of Pier”	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Should Occur Immediately To Reduce Risk Of Damage To Pier.	Signs have been posted on the end of the pier head	N/A – Signage installed
1	0-1 years	Seal Asphalt	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Repair Should Precede Repairs To Structural Components Below Deck To Maximize Lifespan of New Members and Reduce the Rate Of Further Deterioration Of Existing Members.	Approx. 280lm	\$2,870
1	0-1 Years	Repair Bracing	Major Repair, Repairing All Bracing at Once Will Best Utilize Having Construction And Staging Equipment On Site. Additional Efficiencies Are Expected If Coupled With the Banding, Fishplating, Stringer Replacement Program.	Replace Bracing Bolt – 60 Replace Batter Bolt – 30 Replace 12' Member – 7 Replace 24' Member – 48	\$68,860
2	0-2 Years	Lash Fender Piles	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs.	49	\$11,990
3	0-3 Years	Banding, Fishplating, Replace Stringer	Major Repair, Completing All Banding, Fishplating, Stringer Replacement At Once Will Best Utilize Having Construction And Staging Equipment On Site. Additional Efficiencies Are Expected If Coupled With the Bracing Repair Program.	Bands – 22 Fishplate End – 6 Fishplate Entire Beam – 4 Replace 10” of Stringer - 3	\$114,180
3	0-5 Years	Re-Anchor Lamppost	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs.	4	\$1,030
4	0-5 Years (longer if you also close the end of the pier to traffic)	Replace Bent 58	Major Repair, Will Require Considerable Work And Special Equipment Onsite	Entire Bent	\$132,275

*Cost Estimate Excludes Taxes and Mobilization Costs



**PORT HARDY SEAGATE PIER
INSPECTION REPORT**

PREPARED FOR:



PREPARED BY:

ONSITE
Engineering Ltd.

June 30, 2016

TABLE OF CONTENTS

LIST OF FIGURES	II
LIST OF TABLES	II
1.0 INTRODUCTION	1
1.1 SCOPE OF WORK	1
1.2 REFERENCE MATERIAL	1
2.0 PROCEDURES	2
3.0 GEOMETRY	3
3.1 PIER APPROACH	3
3.2 PIER HEAD	3
3.3 FLOATS	4
4.0 RESULTS	5
4.1 BEARING PILES/POSTS	5
4.2 BRACING	5
4.3 CAP BEAMS	6
4.4 STRINGERS	6
4.4 BENT 58	7
4.5 FLOATS	7
5.0 LOAD RATING	8
6.0 RECOMMENDATIONS	9
APPENDIX 2.0. PACIFICUS FIELD NOTES.	15
APPENDIX 4.1.1. ISSUES ASSOCIATED WITH BEARING PILES.	24
APPENDIX 4.2.1. ISSUES ASSOCIATED WITH CROSS BRACING ALONG BENTS.	25
APPENDIX 4.2.2. ISSUES ASSOCIATED WITH CROSS BRACING ALONG PILE COLUMNS.	28
APPENDIX 4.2.3. ISSUES ASSOCIATED WITH HORIZONTAL BRACING.	29

LIST OF FIGURES

FIGURE 3.0.1. Diagram showing pier dimensions, component configurations and the alpha/numeric bent/pile identification system used for the Seagate pier inspection..... 12

Figure 3.1.1. View of pier approach from shore. 12

Figure 3.2.1 View of Southeast corner of pier head. 12

Figure 3.2.2. View of Northwest corner of pier head. 12

Figure 3.3.1. View of the timber floats from the pier head. 13

Figure 4.0.1 View of deteriorated asphalt on pier head..... 13

Figure 4.0.2. View of inadequate bracing that anchors lampposts to pier approach. 13

Figure 4.1.1. An example of a typical split post top at post 6A. 14

Figure 4.2.1. An example of a typical broken cross brace at pile 32D 14

Figure 4.3.1. Cap beam 54 showing signs of rot..... 14

LIST OF TABLES

Table 3.1.1. Typical approach component dimensions..... 3

Table 3.2.1. Typical pier head component dimensions 4

Table 4.1.1. Summary of bearing pile condition. 5

Table 4.2.1. Summary of bracing condition..... 5

Table 4.3.1. Issues associated with cap beams on pile bents..... 6

Table 4.4.1. Issues associated with stringers on pile bents. 6

Table 6.0. Summary of recommendations, priority and expected cost to rectify issues identified during Seagate pier inspection. 10

1.0 INTRODUCTION

On April 27th and 28th, 2016, Onsite Engineering Ltd. (OEL) and Pacificus Biological Services Ltd (Pacificus) conducted an inspection of the Seagate Pier in Port Hardy, BC. The OEL representatives consisted of Jeremy Araki, P.Eng. and Matthew Dickie, EIT. The Pacificus representatives included David Pratt, Ryan Sirges, Tristan Gale, and Adam Harding.

1.1 SCOPE OF WORK

The pier inspection was limited to the pier approach, pier head, gangway and 2 floats. Float 3, buildings, and any other additional structures were excluded from the inspection. OEL inspected the pier components above the current low water at the time and Pacificus inspected the submerged portion of piles and bracing.

1.2 REFERENCE MATERIAL

Prior to the inspection the following documents were provided to OEL:

- Inspection of the general condition of the Municipal Steel Pre-fabricated building located on the Seagate Dock (Coast Guard Building), August 2013.
- Underwater assessment of the Seagate Loading/Unloading Float, Fisherman's Wharf Loading/Unloading Float, Seaplane Float and the Seine Float Anchoring System, August 2010.
- Seagate Approach Inspection, March 2007.
- Port Hardy Wharf and Floats Underwater Inspection, June 1998.

2.0 PROCEDURES

The inspection was performed with a top down approach, visually inspecting the asphalt surfacing, decking, stringers, cap beams, piles and bracing. Sounding/coring of various components was completed where necessary. Where coring occurred a 3/8" hole was drilled to the center of the component. The resulting hole was then plugged with a wooden dowel, soaked in end treatment (a precaution to prevent an opening to provide a pathway for rot to enter the component).

The site was accessed by truck, foot and skiff and site equipment included 2 ipads, 25' tape measure, 100' measuring tape, axe, hammer, and cordless drill with 5/8" drill bit. The precision of all measurements referenced herein are affected by the equipment used and ability to measure the actual component in the field.

The components from bent -1 to 13 were inspected from land during low tide. Components from bents 14 to 58 were inspected by skiff and divers. The skiff was used to inspect components from the low water line at the time to the underside of the decking, using the fluctuation of the tides to access the various component at different elevations. Divers were used to inspect the portion of the pier below water, which included visually inspecting piles and bracing, and prodding the components, connections, and mudline of the piles to estimate section loss due to rot (Appendix 2.0).

3.0 GEOMETRY

The Seagate pier consists of the pier approach, pier head, gangway and 3 floats. All structural components on the underside of the pier consist of creosote treated wood. The decking is made of creosote treated lumber and is surfaced with asphalt. All components are referenced by their associated pile column letter and bent number. The pier components and reference system can be seen in Figure 3.0.1.

3.1 PIER APPROACH

The pier approach is 26' wide and spans 370' from bent -1 to the pier head at bent 38 and can be seen in Figure 3.0.1. The structure consists of decking, supported by stringers, supported by cap beams, supported by piles. Depending on their location, the piles are restrained by various bracing members as shown in Figure 3.0.1.

Typical approach component dimensions are shown in table 3.1.1:

Table 3.1.1. Typical approach component dimensions.

Component	Dimensions
Decking	4" x 12" Typically Spanning 18"
Outside Stringers	12" x 13.5" Typically Spanning 10'
Internal Stringers	6" x 13.5" Typically Spanning 10'
Cap Beams	12" x 13.5" Typically Spanning 8'
Cross Bracing (North/South Bents -1 to 12)	6" x 8" (Length Varies With Pile Height)
Cross Bracing (North/South Bents 13 to 26)	6" x 8" x 12'
Cross Bracing (North/South Bents 26 to 36)	6" x 8" x 24'
Cross Bracing (East/West)	6" x 8" x 24'
Horizontal Bracing (East/West)	6" x 8" x 12' or 24'
Posts/Piles	Range from 11" to 16"+ Diameter (Typically on a 8' by 10' Grid)

3.2 PIER HEAD

The pier head is 72' wide and spans 200' from bent 38 to bent 58 and can be seen below in figure 3.2.1. and 3.2.1. The structure consists of decking, supported on stringers, supported on cap beams, supported on piles. Depending on where, the pier approach piles are restrained by various bracing members and can be seen in Figure 3.0.1.

Typical pier head component dimensions can be seen in table 3.2.1:

Table 3.2.1. Typical pier head component dimensions

Component	Dimensions
Decking	2" x 6" (On Edge) Typically Spanning 18"
Outside Stringers	12" x 13.5" Typically Spanning 10'
Internal Stringers	6" x 13.5" Typically Spanning 10'
Cap Beams	12" x 13.5" Typically Spanning 8'
Cross Bracing (North/South Bents 26 to 36)	6" x 8" x 24'
Cross Bracing (East/West)	6" x 8" x 24'
Horizontal Bracing (East/West)	6" x 8" x 12' or 24'
Horizontal Bracing (North/South)	6" x 8" x 24'
Piles	Range from 11" to 16"+ Diameter (Typically 8' by 10' Grid)
Batter Piles	Range from 11" to 16" Diameter
Fender Piles	Range from 11" to 16" Diameter

3.3 FLOATS

There are three timber floats on the south side of the approach pier that are accessed from the pier via a metal gangway. The gangway extends from the pier approach down onto a 14' by 42' timber float (Float 1), which is connected to a 14' by 100' float (Float 2) (Sutton, 1998). Float 1 is moored to a four pile dolphin on the southern end and is fastened to Float 2. Float two is has been built around 2, 6-pile dolphins and is fastened to Float 1. The third float was gated at the time of the inspection and was not included in the inspection. Floats 1 and 2 can be seen in figure 3.3.1.

4.0 RESULTS

The inspection revealed a number of issues with components on both the pier approach and pier head. Miscellaneous issues indirectly affecting pier components included minor cracking of asphalt on the pier approach, significant deterioration of asphalt on pier head (Figure 4.0.1.), lack of lashing around fender pile dolphins, and inadequate lamppost bracing (Figure 4.0.2.).

4.1 BEARING PILES/POSTS

In general, the piles are in good condition. The only recurring issues with the bearing piles were splitting and checking, an example of which can be seen in figure 4.1.1. Table 4.1.1 summarizes all issues with piles, concerns associated with individual piles can be seen in (Appendix 4.1.1.) In addition to splitting/checking there was a missing pile, a hollow pile, a loose pile, and a cracked concrete post base.

Table 4.1.1. Summary of bearing pile condition.

Section	Condition	Number of Components Affected
Pier Approach	Split	13
Pier Head	Split	12
	Loose Pile	1
	Rotten Pile	1

All connections between batter piles and bearing piles are intact; however, significant corrosion was noted on approximately 50% of these connections.

Inspection of piles below the waterline indicated very little cross sectional loss due to rot. The percent section loss varies from 0 to 5% with a median of 1% section loss (Appendix 2.0).

4.2 BRACING

Numerous cross/horizontal bracing members were missing bolts (corroded and failed), cracked, or rotten. Table 4.2.1 summarizes all issues with bracing. Appendix 4.2.1 outlines all issues with cross bracing that runs along bents. Appendix 4.2.2 outlines all issues with cross bracing that runs along pile columns. Appendix 4.2.3 outlines all issues with horizontal bracing. An example of broken bracing can be seen in figure 4.2.1.

Table 4.2.1. Summary of bracing condition.

Section	Member Type	Condition	Number of Components Affected
Pier Approach	Cross Bracing Running Along Bents	Rotten/Missing	12
		Split	2
		Missing Bottom Bolt	3
	Cross Bracing Running Along Pile Columns	Rotten	3

	Horizontal Bracing	Rotten	3
Pier Head	Cross Bracing Running Along Bents	Rotten	3
		Split	2
		Missing Bottom Bolt	49
	Cross Bracing Running Along Pile Columns	Rotten	4
		Missing Bottom Bolt	1
	Horizontal Bracing	Rotten	13
		Missing Bolt/Blocking	8
	Braced to Wrong Pile	1	

4.3 CAP BEAMS

There were 7 problem cap beams identified during the inspection. Issues included crushed ends and rot. Table 4.3.2 outlines all cap beam issues found during the inspection. Figure 4.3.1. shows an example of a rotten cap beam. It should be noted that problem cap beams only occur at exposed ends and at the bents that are at the ends of the building located on the pier head. It is likely that the encountered issues are the result of exposing the caps to excessive moisture/weather.

Table 4.3.1. Issues associated with cap beams on pile bents.

Section	Bent #	Condition	Recommendation	Comment
Pier Head	42	Split	Fishplate	End Over Pile J Split
	45	End Crushed, Rest Of Beam Suspect	Fishplate	End Over Pile J Crushed, Remaining portion Damp But Not Rotten
	46	End Crushed, Rest Of Beam Suspect	Fishplate	End Over Pile J Crushed, Remaining portion Damp But Not Rotten
	47	Suspect	Fishplate	Beam Damp But Not Rotten.
	54	Rotten	Fishplate	Beam Rotten From Piles D to J, Remainder in Fair Condition
	57	Crushed	Fishplate	End Crushed Over Pile A
	58	Rotten	Closure	No Mooring On Eastern End Of Pier Until Bent Replaced

4.4 STRINGERS

Inspection of stringers on the pier approach and pier head revealed very little signs of damage away from the edges of the pier. The only stringer damage observed occurred on the edges of the pier head at bents 39 and 58. A table outlining where stringer damage occurred can be seen in table 4.4.1.

Table 4.4.1. Issues associated with stringers on pile bents.

Section	Bent #	Number Of Stringers Affected	Condition	Recommendation	Comment
Pier Head	39	3	Cracked and Crushed	Replace	End Over Pile G Cracked, Next Stringer To the South Cracked, Stringer Over Pile F Crushed
	58	8	Rotten, Cracked and Crushed	Replace	8 Problem Stringers Identified on Bent, Include Rotten, Crushed and Cracked Stringers

--	--	--	--	--	--

4.4 BENT 58

Many of the major issues encountered occurred at bent 58. Overall bent 58 is in poor condition and requires considerable work to ensure this portion of the pier functions adequately. Issues present at bent 58 include a mooring cleat fastened through only the pier decking, 8 problem stringers (rotten/crushed/cracked), a rotten cap beam, a hollow pile, a missing pile, a split pile and rotten fender piles which are not lashed.

4.5 FLOATS

Timber floats 1 and 2 were inspected and found to be in generally good condition and require only minor improvements. The Northeastern corner of Float 2 sits low in the water. Other concerns regarding wear occur at the connections between the two floats and around the dolphins that hold float 2 in place.

5.0 LOAD RATING

OEL completed a load analysis for vehicular traffic on the pier approach and head and mooring load on the pier head. Vehicle loading generally follows CAN/CSA-S6 and the BCL-625 design vehicle was used for axle loading. Obviously, the maximum sized vehicle will also be governed by the geometry of the pier. Mooring forces were calculated using a 60m long, 9m high (above water) vessel. A maximum 1m high wave with 0.75kPa wind pressure combined load was used as the limiting condition.

The pier pile caps and beams are capable of withstanding the 140kN maximum axle load associated with a BCL-625 design vehicle. Due to vehicle tracking, the actual maximum sized vehicle is likely limited to a three axle truck. However, a tractor/trailer may be able to back on and drive off of the structure on the north side of the pier head. Design values and factors of safety are all from CAN/CSA-S6 and CAS/CSA-O86 and were not reduced to achieve these ratings.

The analysis of the above mentioned vessel was completed using the assumption that the deck of the pier head provides adequate transverse stiffness, and the internal bracing is fully functional. Further, only the piles in the nearest half of the pier head were assumed for resistance, although the entire pier head is required to provide overturning resistance given the very shallow pile penetration (reported as 4'-6' by the contractor). Ignoring the batter piles, the structure is not quite capable of safely housing the design vessel. Therefore, the batter piles, and their connection at the top, are of utmost importance to achieve the full mooring load capacity. Further, the suggested repair to the bracing and batter pile bolts herein are critical to the applicability of this load rating. No global factor of safety was applied to this rating. However, in our experience, the wood strength values from the above CAN/CSA references contain a healthy factor of safety when applied to full logs (rather than small dimensional lumber for which they are tabulated). Further, our assumption in wind loading for the above vessel was very conservative. These points, combined with the past performance of the structure and the upcoming repairs, give confidence in the ability of the structure to safely moor large vessels.

Until the end of the pier head is repaired, the signage for no mooring should remain. Further, it is suggested that, in the event of a large storm, only one large vessel should be moored to the pier head.

6.0 RECOMMENDATIONS

Immediately, the mooring cleat on bent 58 should be removed and the pier head should be signed to ensure no mooring of vessels on the Eastern end of the pier. Before mooring is permitted on the eastern end of the pier head, bent 58 must be replaced. Bent replacement will require a row of new piles, driven inside the old piles, and a new cap beam should be placed on the new piles. The stringers and decking between bents 57 and 58 may require replacement at this time to facilitate driving piles.

Internal cap beams should be repaired by fishplating identified problem cap beams and the supporting piles the caps rest on. This will allow the stringers to be supported by the fishplate rather than the existing cap beam. The fishplating, banding and stringer replacement program should be implemented at the same time to further utilize the same system.

Bracing and bolt replacement should occur at the same time as both will require the same tools and may be restricted by tidal access. All bolts at the tops of the batter piles must be replaced. Where deterioration is noted in the batter pile or the vertical pile around the connection, an alternate location for the connection must be found (i.e. the next pile in, or connecting the batter pile to the cap beam). These batter piles are critical to the performance of the pier.

Asphalt sealing is a high priority as it protects all components below the deck. It should be noted that special attention should be paid to the seal around the coast guard building as problems with cap beam rot appear to be a direct result of water ingress around the building. Asphalt sealant is an acceptable medium for repairs to both asphalt cracks and the sealant around the coast guard building.

The current system used to anchor the lampposts is ineffective. The current C-channel bracing used should be replaced with 10"x20"x1/2" steel plating or 20" long 10" C-channel. If C-channel is used it is important that the flange is facing down when installed. This proposed "C" channel orientation is to prevent the flanges from cutting into the stringers it braces against as the bolts are tightened.

The fender piles should be lashed. This can be done from the pier deck by using a hiab to tighten/install lashing.

Only minor work is required on the floats. The excess clearance around the dolphins float 2 is secured by should be reduced by building up the inside of their opening with creosote treated timbers to reduce play in both the north/south and east/west directions to 2". The connection between floats 1 and 2 should be reduced to allow for a maximum of 4" of play. The foam billet under the northeast corner should be replaced.

A summary of the proposed repairs, their priority and their expected costs can be seen in table 6.0.1. It should be stressed that all hardware used in repairs should be galvanized or stainless steel, all timbers/piles be creosote treated, and all newly installed stringers, cap beams, and piles have their exposed ends covered with flashing to prevent rot.

Table 6.0. Summary of recommendations, priority and expected cost to rectify issues identified during Seagate pier inspection.

Project #	Timing	Repair	Additional Timing Information	Number Of Components Affected	Estimated Cost (\$)*
N/A	N/A – Repairs In Progress	Replace Float Billet	N/A – Repairs In Progress	1	N/A – Repairs In Progress
	N/A – Repairs In Progress	Reduce Play Around Float Dolphins	N/A – Repairs In Progress	2	N/A – Repairs In Progress
1	Immediately	Remove Mooring Cleat on Eastern End Of Pier	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Should Occur Immediately To Reduce Risk Of Damage To Pier.	1	\$450
1	Immediately	Sign “No Mooring At End Of Pier”	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Should Occur Immediately To Reduce Risk Of Damage To Pier.	Signs have been posted on the end of the pier head	N/A – Signage installed
1	0-1 years	Seal Asphalt	Minor Repair, No Significant Benefit Completing Repair Concurrently With Other Repairs. Repair Should Precede Repairs To Structural Components Below Deck To Maximize Lifespan of New Members and Reduce the Rate Of Further Deterioration Of Existing Members.	Approx. 280lm	\$2,870
1	0-1 Years	Repair Bracing	Major Repair, Repairing All Bracing at Once Will Best Utilize Having Construction And Staging Equipment On Site. Additional Efficiencies Are Expected If Coupled With the Banding, Fishplating, Stringer	Replace Bracing Bolt – 60 Replace Batter Bolt – 30 Replace 12' Member – 7	\$68,860

A qualified registered professional should complete construction inspections during the commencement of the bent 58 replacement program, the bracing program, and the banding, fishplating, and stringer replacement program. All repairs should be inspected by a qualified registered professional upon completion.

Sincerely,
Onsite Engineering Ltd.

Matthew Dickie
Matthew Dickie, EIT
Project Engineer

Reviewed by:



Jeremy Araki, P. Eng
Supervising Engineer

FIGURE 3.0.1. Diagram showing pier dimensions, component configurations and the alpha/numeric bent/pile identification system used for the Seagate pier inspection.



Figure 3.1.1.

View of pier approach from shore.

Photo April 27, 2016



Figure 3.2.1.

View of Southeast corner of pier head.

Photo April 28, 2016



Figure 3.2.2.

View of Northwest corner of pier head.

Photo April 28, 2016



Figure 3.3.1.

View of the timber floats from the pier head.

Photo April 28, 2016



Figure 4.0.1.

View of deteriorated asphalt on pier head.

Photo April 27, 2016



Figure 4.0.2.

View of inadequate bracing that anchors lampposts to pier approach.

Photo April 27 2016



Figure 4.1.1.

An example of a typical split post top at post 6A.

Photo April 27, 2016



Figure 4.2.1.

An example of a typical broken cross brace at pile 32D


Photo April 27 2016




Figure 4.3.1.

Cap beam 54 showing signs of rot.

Photo April 27, 2016



PLAN VIEW FOR THE IDENTIFICATION OF PIER COMPONENTS FOR THE SEAGATE PIER HEAD
1" = 40'



PROFILE VIEW FOR THE IDENTIFICATION OF PIER COMPONENTS FOR THE SEAGATE PIER HEAD
1" = 40'

FIGURE 3.0.1. DIAGRAM SHOWING PIER DIMENSIONS, COMPONENT CONFIGURATIONS AND THE ALPHANUMERIC BENT/PILE IDENTIFICATION SYSTEM USED FOR THE SEAGATE PIER INSPECTION.

PREPARED FOR:

PREPARED BY:




ONSITE
ENGINEERING LTD.
COASTAL OPERATIONS
1040 CEDAR STREET
CAMPBELL RIVER, BC, V9W7E2
PH: 250-287-8174 FAX: 866-235-8943

DWG No. 1439-1-SEAGATEPIER-001


SHEET: 1 OF 4

DESIGN BY: N/A
DESIGN DATE: N/A
REVIEWED BY: N/A
DRAWN BY: MATTHEW DICKIE, EIT
SITE VISIT: ONSITE ENGINEERING LTD.
SITE VISIT DATES: APRIL 27/28, 2016
FILE NAME: SEAGATEPIER.DWG
SCALE: AS NOTED
REVISION NUMBER:
REVISION DATE:
ALL MEASUREMENTS IN INCHES UNLESS OTHERWISE NOTED.





SECTION A
SCALE 1"=10'



SECTION B
SCALE 1"=10'



SECTION C
SCALE 1"=10'



DETAIL 1
SCALE 1"=10'

DETAIL 2
SCALE 1"=10'

DETAIL 3
SCALE 1"=10'

PREPARED FOR:



PREPARED BY:

ONSITE
ENGINEERING LTD.
COASTAL OPERATIONS
1040 CEDAR STREET
CAMPBELL RIVER, BC, V9W7E2
PH: 250-287-9174 FAX: 866-235-6943


FIGURE 3.0.1. DIAGRAM SHOWING PIER DIMENSIONS,
COMPONENT CONFIGURATIONS AND THE ALPHANUMERIC
BENT/PILE IDENTIFICATION SYSTEM USED FOR THE SEAGATE
PIER INSPECTION.

DWG No. 1439-1-SEAGATEPIER-002 SHEET: 2 OF 4

DESIGN BY: N/A
DESIGN DATE: N/A
REVIEWED BY: N/A
DRAWN BY: MATTHEW DICKIE, EIT
SITE VISIT: ONSITE ENGINEERING LTD.
SITE VISIT DATES: APRIL 27/28, 2016
FILE NAME: SEAGATEPIER.DWG
SCALE: AS NOTED
REVISION NUMBER:
REVISION DATE:
ALL MEASUREMENTS IN INCHES UNLESS OTHERWISE NOTED.

SECTION D
SCALE 1"=10'
1

DETAIL 4
SCALE 1"=10'
1



PREPARED FOR:

PREPARED BY:




ONSITE
ENGINEERING LTD.
COASTAL OPERATIONS
1040 CEDAR STREET
CAMPBELL RIVER, BC, V9W7E2
PH: 250-287-9174 FAX: 866-235-8943

FIGURE 3.0.1. DIAGRAM SHOWING PIER DIMENSIONS,
COMPONENT CONFIGURATIONS AND THE ALPHA/NUMERIC
BENT/PILE IDENTIFICATION SYSTEM USED FOR THE SEAGATE
PIER INSPECTION.

DWG No: 1439-1-SEAGATEPIER-003

SHEET: 3 OF 4

DESIGN BY: N/A
DESIGN DATE: N/A
REVIEWED BY: N/A
DRAWN BY: MATTHEW DICKIE, EIT
SITE VISIT: ONSITE ENGINEERING LTD.
SITE VISIT DATES: APRIL 27/28, 2016
FILE NAME: SEAGATEPIER.DWG
SCALE: AS NOTED
REVISION NUMBER:
REVISION DATE:
ALL MEASUREMENTS IN INCHES UNLESS OTHERWISE NOTED.



PREPARED FOR:

PREPARED BY:



ONSITE
ENGINEERING LTD.
COASTAL OPERATIONS
1040 CEDAR STREET
CAMPBELL RIVER, BC, V9W 7E2
PH: 250-287-9174 FAX: 866-235-6943

**FIGURE 3.0.1. DIAGRAM SHOWING PIER DIMENSIONS,
COMPONENT CONFIGURATIONS AND THE ALPHANUMERIC
BENT/PILE IDENTIFICATION SYSTEM USED FOR THE SEAGATE
PIER INSPECTION.**

DWG No: 1439-1-SEAGATEPIER-004

SHEET: 4 OF 4

DESIGN BY: N/A
DESIGN DATE: N/A
REVIEWED BY: N/A
DRAWN BY: MATTHEW DICKIE, EIT
SITE VISIT: ONSITE ENGINEERING LTD.
SITE VISIT DATES: APRIL 27/28, 2016
FILE NAME: SEAGATEPIER.DWG
SCALE: AS NOTED
REVISION NUMBER:
REVISION DATE:
ALL MEASUREMENTS IN INCHES UNLESS OTHERWISE NOTED.

APPENDIX 2.0. PACIFICUS FIELD NOTES.

Seagate Wharf Piling Inspection

*all others given as percent loss of load-bearing pile

*fender piles given as fraction of piles in grouping rotted out

Piling #	% loss or number of fenders compromised	
15A	1	
15B	1	
16A	3	
16B	1	
16C	0	
16D	0	
17A	1	
17B	1	
17C	0	
17D	0	
18A	1	
18B	1	
18C	0	
18D	0	
19A	1" X 2" bore hole	
19B	1	
19C	1	
19D	0	
20A	1	
20B	1	
20C	4	
20D	0	
21A	0	
21B	5	
21C	0	
21D	1	
22A	1	
22B	1	
22C	0	
22D	0	
23A	0	
23B	1	
23C	0	
23D	0	
24A	1	
24B	cross member bolt rusted	

Piling #	% loss or number of fenders compromised	
24C	0	
24D	0	
25A	0	
25B	cross member bolt rusted	
25C	0/0	
25D	1	
26A	1	
26B	1, cross member bolt missing, cross member is loose	
26C	0	
26D	0	
27A	1	
27B	1	
27C	0	
27D	0	
28A	1	
28B	1	
28C	0	
28D	0	
29A	1	
29B	3	
29C	0	
29D	0/2	
30A	1	
30B	1	
30C	0	
30D	0/0	
31A	1	
31B	1	
31C	2	
31D	0	
32A	5	
32B	1	
32C	1	
32D	0	
33A	1/1/1	
33B	1	
33C	0	
33D	0	
34A	1	
34B	1	

Piling #	% loss or number of fenders compromised	
34C	0	
34D	1	
35B	3	
35C	0	
35D	0	
36A	1	
36B	0	
36C	1/1	
36D	2/1	
36E	2	
36F	2	
36A-F	0/4	*fender*
39A-F	0/3	*fender*
39A	0	
39B	3	
39C	1/1	
39D	0/0	
39E	0	
39F	0	
39G	0	
39H	2	
39I	5	
39J	2	
39J-F	0/3	*fender*
40A-F	0/4	*fender*
40A	1	
40B	1	
40C	0	
40D	0	
40E	0	
40F	0	
40G	0	
40H	0	
40I	1	
40J	1	
40J-F	0/4	*fender*
41A-F	0/3	*fender*
41A	0	
41B	0	
41C	3/0	

Piling #	% loss or number of fenders compromised	
41D	2	
41E	2	
41F	0	
41G	0	
41H	0	
41I	3	
41J	0	
41J-F	0/3	*fender*
42A-F	0/3	*fender*
42A	1	
42B	3	
42C	2	
42D	1	
42E	1	
42F	2	
42G	2	
42H	1	
42I	2	
42J	2	
42J-F	0/3	*fender*
43A-F	0/3	*fender*
43A	1	
43B	1	
43C	0/3	
43D	0	
43E	0	
43F	1	
43G	0	
43H	0/0	
43I	0	
43J	0	
43J-F	0/3	*fender*
44A-F	0/3	*fender*
44A	2	
44B	2	
44C	2	
44D	5	
44E		
44F	0	
44G	1	

Piling #	% loss or number of fenders compromised	
44H	2	
44I	0	
44J	2	
44J-F	0/3	*fender*
45A-F	0/3	*fender*
45A	1	
45B	1	
45C	0/0	
45D	1	
45E	0	
45F	0	
45G	0	
45H	0/0	
45I	0	
45J	0	
45J-F	0/3	*fender*
46A-F	0/3	*fender*
46A	0	
46B	5	
46C	2	
46D	1	
46E	2	
46F	2	
46G	3	
46H	3	
46I	1	
46J	0	
46J-F	0/3	*fender*
47A-F	0/4	*fender*
47A	0	
47B	3/0	
47C	0/0	
47D	0/0	
47E	1	
47F	3	
47G	0	
47H	0/0	
47I	0	
47J	0	
47J-F	0/3	*fender*

Piling #	% loss or number of fenders compromised	
48A-F	0/5	*fender*
48A	2	
48B	1	
48C	1	
48D	0	
48E	2	
48F	3	
48G	2	
48H	1	
48I	2	
48J	1	
48J-F	0/3	*fender*
49A-F	0/3	*fender*
49A	2	
49B	1	
49C	1	
49D	1	
49E	0	
49F	0	
49G	0	
49H	3	
49I	0	
49J		
49J-F	0/3	*fender*
50A-F	0/5	*fender*
50A	2	
50B	2	
50C	1	
50D	2	
50E	4	
50F	2	
50G	2	
50H	1	
50I	2	
50J	3	
50J-F	1/4	*fender*
51A-F	0/3	*fender*
51A	0	
51B	0	
51C	0	

Piling #	% loss or number of fenders compromised	
51D	1	
51E	1	
51F		
51G	3	
51H	1	
51I	0	
51J	1	
51J-F	0/3	*fender*
52A-F	0/5	*fender*
52A	2	
52B	2	
52C	2	
52D	3	
52E	4	
52F	1	
52G	2	
52H	1	
52I	2	
52J	3	
52J-F	0/3	*fender*
53A-F	0/3	*fender*
53A	1	
53B	0	
53C	1	
53D	1	
53E	0	
53F	3	
53G	1/1	
53H	1	
53I	2	
53J	0	
53J-F	0/3	*fender*
54A-F	0/5	*fender*
54A	1	
54B	2	
54C	1	
54D	1	
54E	1	
54F	2	
54G	1	

Piling #	% loss or number of fenders compromised	
54H	1	
54I	1	
54J	1	
54J-F	0/3	*fender*
55A-F	0/3	*fender*
55A	1	
55B	1	
55C	1	
55D	1	
55E	1	
55F	1	
55G	1	
55H	0	
55I	0	
55J	0	
55J-F	0/4	*fender*
56A-F	0/5	*fender*
56A	2	
56B	2	
56C	1	
56D	2	
56E	1	
56F	1	
56G	2	
56H	1	
56I	1/2	
56J	1	
56J-F	0/3	*fender*
57A-F	0/4	*fender*
57A	0	
57B	0	
57C	1	
57D	1	
57E	0	
57F	1	
57G	0	
57H	1	
57I	1	
57J	1	
57J-F	0/3	*fender*

Piling #	% loss or number of fenders compromised	
58A	2	
58B	2	
58C	3 - hollow?	
58D	1	
58E	1	
58F	1	
58G	2	
58H	1	
58I	1	
58J	2	
End-A	0/7	*fender*
End-B	0/3	*fender*
End-C	0/5	*fender*
End-D	0/3	*fender*
End-E	0/3	*fender*
End-F	0/3	*fender*
End-G	0/4	*fender*
End-H	0/3	*fender*
End-I	0/5	*fender*
End-J	0/8	*fender*
CG Float N	0/6	*group*
CG Float SW	0/4	*group*
CG Float SE	0/6	*group*

APPENDIX 4.1.1. ISSUES ASSOCIATED WITH BEARING PILES.

Section	Bent #	Pile ID	Issue	Repair	Comment
Pier Approach	6	A	Split	Band	Split But Solid
	11	C	Split	Band	
	12	C	Minor Split	Band	
	16	D	Split	Band	
	17	A	Checked	Band	
	21	A	Split	Band	
	22	B	Split	Band	
	22	C	Split	Band	
	24	C	Minor Check	Monitor	
	26	D	Checked	Band	
	28	D	Checked	Band	
	31	A	Severely Split	Band	
	32	A	Minor Check	Band	
Pier Head	39	H	Split	Band	
	39	J	Split	Band	Replace Band With Heavier Band
	40	A	Severely Split	Install Fishplating	Split And Banded, Existing Banding Ineffective
	43	A	Severely Split	Install Fish Plating Or Replace	Banded and Split, Existing Banding Ineffective, Split Extends 2+m From Top.
	43	J	Split	Band And Install Fishplating	
	44	A	Split	Band	Replace Band With Heavier Band
	47	H	Split	Band And Replace Bolts	Replace Band With Heavier Band, Replace Bolts
	47	I	Split	Band	
	51	D	Pile Loose	Add Horizontal Bracing	Add Horizontal from 51D to 52D
	51	F	Split	Band	
	51	I	Split	Band	
	53	J	Severely Split	Band Or Install Fishplating	
	58	C	Rotten	Replace	Pile Is Hollow
58	G	Split	Band		

Section	Bent #	Pile ID	Issue	Repair	Comment
	58	I	Missing	Replace	

APPENDIX 4.2.1. ISSUES ASSOCIATED WITH CROSS BRACING ALONG BENTS.

Section	Bent #	From Pile " " To Pile " "	Issue	Other Issue	Repair	Comment
Pier Approach	12	C-D	Missing		Replace	
	15	C-D	Missing		Replace	
	16	A-B	Rotten		Replace	
	17	A-B	Rotten		Replace	
	18	A-B	Rotten		Replace	
	19	C-D	Missing		Replace	
	21	A-B	Split		Replace	
	24	B-D	Loose Bottom Bolt		Replace Bolt	
	25	B-D	Loose Bottom Bolt		Replace Bolt	
	26	B-D	Loose Bottom Bolt	Split	Replace	
	29	A-C	Rotten		Replace	
	31	A-C	Rotten		Replace	
	31	B-D	Rotten		Replace	
	32	B-D	Rotten		Replace	
	33	B-D	Rotten		Replace	
35	A-C	Rotten		Replace		
Pier Head	40	B-D	Loose Bottom Bolt		Replace Bolt	
	40	D-B	Loose Bottom Bolt	Split	Replace	
	40	G-I	Loose		Replace	

Section	Bent #	From Pile " " To Pile " "	Issue	Other Issue	Repair	Comment
			Bottom Bolt		Bolt	
	41	B-D	Loose Bottom Bolt		Replace Bolt	
	41	D-B	Checked		Replace	
	41	F-H	Loose Bottom Bolt		Replace Bolt	
	41	J-H	Loose Bottom Bolt		Replace Bolt	
	42	A-C	Loose Bottom Bolt		Replace Bolt	
	42	F-H	Loose Bottom Bolt		Replace Bolt	
	42	G-I	Loose Bottom Bolt		Replace Bolt	
	42	J-H	Loose Bottom Bolt		Replace Bolt	
	43	A-C	Loose Bottom Bolt		Replace Bolt	
	43	D-B	Loose Bottom Bolt		Replace Bolt	
	43	F-H	Loose Bottom Bolt		Replace Bolt	
	43	G-I	Loose Bottom Bolt		Replace Bolt	
	43	J-H	Loose Bottom Bolt		Replace Bolt	
	44	B-D	Loose Bottom Bolt		Replace Bolt	
	44	F-H	Loose Bottom Bolt		Replace Bolt	
	44	J-H	Loose Bottom Bolt		Replace Bolt	
	45	G-I	Loose Bottom Bolt		Replace Bolt	
	46	A-C	Rotten		Replace	
	46	B-D	Rotten		Replace	
	46	E-C	Loose Bottom Bolt		Replace Bolt	
	46	F-H	Loose Bottom Bolt		Replace Bolt	
	46	G-I	Loose Bottom Bolt		Replace Bolt	

Section	Bent #	From Pile " " - To Pile " "	Issue	Other Issue	Repair	Comment
	46	I-G	Loose Bottom Bolt		Replace Bolt	
	46	J-H	Loose Bottom Bolt		Replace Bolt	
	47	B-D	Loose Bottom Bolt		Replace Bolt	
	47	E-C	Loose Bottom Bolt		Replace Bolt	
	47	G-I	Loose Bottom Bolt		Replace Bolt	
	47	J-H	Loose Bottom Bolt		Replace Bolt	
	48	E-C	Rotten		Replace	
	48	F-H	Loose Bottom Bolt		Replace Bolt	
	48	G-I	Loose Bottom Bolt		Replace Bolt	
	48	I-G	Loose Bottom Bolt		Replace Bolt	
	48	J-H	Loose Bottom Bolt		Replace Bolt	
	49	B-D	Loose Bottom Bolt		Replace Bolt	
	49	D-B	Loose Bottom Bolt		Replace Bolt	
	49	F-H	Loose Bottom Bolt		Replace Bolt	
	50	D-B	Loose Bottom Bolt		Replace Bolt	
	50	F-H	Loose Bottom Bolt		Replace Bolt	
	50	G-I	Loose Bottom Bolt		Replace Bolt	
	51	B-D	Loose Bottom Bolt		Replace Bolt	
	51	I-G	Loose Bottom Bolt		Replace Bolt	
	52	B-D	Loose Bottom Bolt		Replace Bolt	
	53	E-C	Loose Bottom Bolt		Replace Bolt	
	54	B-D	Loose Bottom Bolt		Replace Bolt	

Section	Bent #	From Pile " " To Pile " "	Issue	Other Issue	Repair	Comment
	54	F-H	Loose Bottom Bolt		Replace Bolt	
	55	A-C	Loose Bottom Bolt		Replace Bolt	
	55	E-C	Loose Bottom Bolt		Replace Bolt	
	55	F-H	Loose Bottom Bolt		Replace Bolt	
	56	B-D	Loose Bottom Bolt		Replace Bolt	
	57	B-D	Rotten		Replace	Broken Off
	57	E-C	Loose Bottom Bolt		Replace Bolt	
	57	G-I	Loose Bottom Bolt		Replace Bolt	

APPENDIX 4.2.2. ISSUES ASSOCIATED WITH CROSS BRACING ALONG PILE COLUMNS.

Section	From Bent " " To Bent " "	Pile ID	Issue	Repair
Pier Approach	27-28	B	Rotten	Replace
	27-28	C	Rotten	Replace
	33-34	B	Rotten	Replace
Pier Head	44-45	E	Rotten	Replace
	44-45	F	Rotten	Replace
	44-45	I	Rotten	Replace
	47-48	H	Rotten	Replace
	57-58	H	Loose Bolt	Replace Bolt

APPENDIX 4.2.3. ISSUES ASSOCIATED WITH HORIZONTAL BRACING.

Section	From Bent " " to " "		From Pile " " to " "		Issue	Repair
Pier Approach	26	27	C	C	Rotten	Replace
	31	33	D	D	Rotten	Replace
	34	36	B	B	Rotten	Replace
Pier Head	39	40	J	J	Rotten	Replace
	47	49	J	J	Rotten	Replace
	49	51	E	E	Loose Bolt	Replace
	50	50	H	J	Loose Bolt	Replace bolt
	50	52	A	A	Loose Bolt	Replace Bolt
	50	51	J	J	Rotten	Replace
	51	51	I	J	Rotten	Replace
	52	53	H	H	Loose Bolt	Replace Blocking And Bolt
	52	53	J	J	Blocking Rotten	Replace Blocking And Bolt
	50	52	I	I	Rotten	Replace
	52	52	H	J	Rotten	Replace
	53	53	I	I	Blocking Rotten	Replace Blocking and Bolt
	54	54	H	J	Missing	Replace
	53	55	D	D	Rotten	Replace
	56	56	H	J	Loose Bolt	Replace Bolt
	56	57	A	A	Loose Bolt	Replace Bolt
	58	58	H	J	Missing	Replace
57	58	I	I	Braced to Old Pile	Brace to New Pile	



DISTRICT OF PORT HARDY

STAFF REPORT



DATE: July 15, 2016
TO: Mayor and Councillors
FROM: Abbas Farahbakhsh, Director of Operational Services
RE: Museum's Recent Security Issues

PURPOSE

The purpose of this report is to discuss recent security issues at the Museum and evaluate different options to possibly remedy the problem or to minimize the financial impact on the District and emotional stress on Museum staff.

ANALYSIS

From April of 2016 until July of 2016 the security at the Museum building has been compromised five times. Each time the building, the stands and shelving inside have sustained damage and some valuable items have been stolen. It seems that the gift shop's jewellery display case is the thieves favorite target, so far according to the police report an estimated \$4,000 in Aboriginal jewelry and merchandise have been stolen and at least \$1,000 worth of internal damage have been repaired.

External damages consist of broken windows and other cosmetic damages to the facade of the building. Each act of break and entering has resulted in boarding of the broken windows and eventual replacement of the broken windows. Thus far, without considering staff time, we have spent in a neighbourhood of \$12,000 towards fixing the external damages including approximately \$5,000 for purchase and installation of security cameras.





Staff has investigated ways for strengthening the security of the building and the following options are the results of our efforts.

Option 1: Do nothing:

This option will carry no initial cost and will provide no solution to the current challenge in hand. This will result in the deterioration of trust between museum staff, public and the district. This can result in lack of public confidence in the safety and security of the donated artifacts. In some cases this may result in the demand for removal or return of these items and perhaps public hesitation for future donation of such culturally important arts.

Option 2: Stronger Glass:

All broken windows were replaced with stronger tempered glass however at the end stronger glass did not offer much of a fight against large rocks that were used by the thieves. We believe a combination of stronger glass and window shutters or window security bars could provide enough deterrence.

It must be noted that there are some windows boarded up, eventually all boards must be replaced with a new stronger type glass (this could cost additional \$3,000 to \$4,000).

Option 3: External Window Shutters:

External window shutters will provide maximum protection for the building and its contents, pending on the pattern and kind of shutters chosen, they can provide solid or semi solid visual barrier to the content inside the museum. Most shutters can be equipped with power operated opener for fast and convenient operation of the shutters.

The initial cost for this option may be more than other options but it can provide the most effective protection for the building, windows and museum content (however these devices could be easily vandalized such as spray paint or scratches, etc.).

Staff has secured two quotes for supply and installation of window shutters ranging from \$15,453.90 to \$22,813.00 plus taxes and additional electrical hookup for remote operation of the shutters.

Option 4: External Security Bars:

External window security bars could provide a similar level of protection for the museum content as the external window shutters, but will provide no protection for the glass and the building. This

option does not lend itself to vandalism due to limited surface area of the bars. This option will provide visual inspection that can be useful during night and after hours.

Staff have secured one quote from local welding shop to fabricate and supply window bars for \$3,600 plus taxes, however details as to the style and specifications for this work are not finalized and pending on details for the project the price may increase.

FINANCIAL IMPLICATIONS

All associated repair costs as well as additional security measure costs will be charged to the Museum Capital budget with funding from the Building Reserve, knowing that we are already over budget in the Museum operational budget. Financial implications range from \$0.00 to \$30,000.00 dependant on the chosen option.

STAFF RECOMMENDATION

Staff recommends that Council considers either Option #3 (External Window Shutters) or Option #4 (External Security Bars); for a budget of up to \$30,000. The \$10,000 established in the 2016-2020 Financial Plan for Museum renovations be redirected towards the security project plus additional funds be withdrawn from the Building Reserve Fund.

Respectfully submitted,

I agree with the recommendation

Signed



Abbas Farahbakhsh
Director of Operational Services

Signed



Allison McCarrick
Chief Administrative Officer